

1994 Challenger 601-3R

Serial Number 5146 Registration Number: Private (As of Aug 08, 2015)

AIRFRAME: Hours Since New: 5586.6 Landings 2963 ENGINES: GE CF34-3A1 Engines On JSSI Platinum (\$404.79 /hr) APU: Garrett GTCP 36-150 CL S/N P-438C On MSP Gold (83.61/hr) **MAINTENANCE:** Engines-JSSI **APU-Honeywell MSP** 60 Inspection Completed Nov 2013 APU upgraded to GTCP 36-150CL **CPCP** Inspections Nov 2013 120 Month landing Gear Inspection Completed Nov 2013 Next 60 Month Inspection due in Sep 2018 Next 4800 hour Inspection due at 9600 hours Next 2400 hour Inspection due at 6781 hours AVIONICS AND EQUIPMENT: COM: Dual Collins VHF-22C w/8.33 KHz Spacing NAV: Dual Collins VIR-32 w/FM Immunity FDS: Honeywell SPZ-8000 A/P: Honeywell SPZ-8000 XPNDR: Dual Collins TDR-94D Mode S Enhanced w/Flight ID ADF: Dual Collins ADF-462 DME: Dual Collins DME-42 ADC: Dual Honeywell AZ-810 FMS: Dual Honeywell NZ-2000, Version NZ6.0 CDU: Dual Honeywell CD-820 Specifications/Descriptions are provided as introductory information and do not constitute representations or warranties of Executive Aircraft Services, Inc. or Executive Aircraft Services, Inc. client(s). Accordingly, you should rely on your own inspection of the aircraft. Any proposed transaction is subject to final execution of a contract acceptable in form and substance to Executive Aircraft Services, Inc., its client(s), and their counsel. 416-542-1059 Phone 🧇 416-564-1600 Cell 💎 416-981-7674 Fax

info@executive-aircraft.com



GPS: Dual Honeywell Integrated AFIS: Allied Signal VHF Only STCOM: Aircell Axxess (2 Channel, 3 Handsets) HFCOM: Dual Collins HF-9000 w/MOTOROLA SELCAL EFIS: Honeywell EDZ-815 5-tube RADAR: Honeywell Primus WU-870 Color w/Turbulence TCAS: Honeywell Primus WU-870 Color w/Turbulence TCAS: Honeywell TCAS 2000 w/Change 7.1 ELT: Artex 406 MHz w/NAV Interface EGPWS: Honeywell Mark V EGPWS LRNAV: Dual Honeywell LASEREF IRUs w/LASERTRAK Control FDR: Loral (L3) F-1000 w/Teledyne FDAU CVR: L3 A100 RADALT: Dual Honeywell RT-300 AUDIO PAN: Dual AVTECH 1509-1-3 Nav Database Update System: Honeywell DL-950 USB Interface

Additional Equipment & Features:

Aircell Axxess & SSB Rockwell Collins "Venue" CMS w/ WIFI 6 115VAC 60 Hz Electrical Outlets (1 FWD Closet, 1 Galley, 3 Cabin, 1 Lav) Dual DAVTRON M811B Chronometers Therapeutic Oxygen

OPTIONAL EQUIPMENT/FEATURES

Three additional Cabin WindowsGrimes LowDorne & Margolin 8.1 ELTLED LightinLH Engine Pylon Down Light for BaggageLogo LightinSmoke Detector in Baggage CompartmentAVS AerialAirshow 4000Itouch RenHigh temp OvenHot CupTherapeutic Oxygen Outlet in CabinWifi- with HLadderTossingtonTow barAft EquipmGames portIpod Jack INew Cabin Sound System optimized at each cabin seat location3 M Sound proofingGalley fride

Grimes Lower Beacon Light Strobes LED Lighting Logo Lights AVS Aerial View System Itouch Remote Control of Cabin Hot Cup Wifi- with High Speed Data Tossington Jump Seat Aft Equipment Bay Storage Box Ipod Jack Panel eat location Galley fridge

2

Specifications/Descriptions are provided as introductory information and do not constitute representations or warranties of Executive Aircraft Services, Inc. or Executive Aircraft Services, Inc. client(s). Accordingly, you should rely on your own inspection of the aircraft. Any proposed transaction is subject to final execution of a contract acceptable in form and substance to Executive Aircraft Services, Inc., its client(s), and their counsel.



New November 2013

Completed at Jet Aviation, St. Louis. 12 passenger interior configuration: four club chairs forward; aft cabin has a four place divan on the right side and a four place dinette on the left side. A large forward galley and aft lavatory. 1 Tossington Jumpseat. Forward single club chairs are grey tone calfskin leather. Carpet is a medium grey pile. The divans are finished in a multi-color pattern. Galley and Lavatory countertop is Corian. Chairs and divan are fire blocked to comply with FAR Part 135 requirements. The wood throughout the aircraft is a high-gloss. The Headliner has been changed to a 604 style. **Interior Fire-blocked**.

The cabin is controlled by Rockwell Collins Venue system at individual seat through I-touch controllers or at Galley by a 10.6" Galley touch screen. Located on the forward bulkhead is a 24" Rosen HD monitor and on the rear bulkhead a 26" HD monitor. The media center with integrated Blue Ray, Apple TV, Data storage Server, CD, MP3 player can be played/displayed throughout the cabin as required. New Alto Aviation cabin sound system has been installed ad audio optimized at each of the passenger location. A 3M soundproofing package has been installed to quite the cabin.

Cabin Galley is equipped with a refrigerator, Tia Microwave and Espresso maker, all new in November 2013.

EXTERIOR:

White with Grey accent stripes running the length of the fuselage. (New Nov 2013)

Specifications/Descriptions are provided as introductory information and do not constitute representations or warranties of Executive Aircraft Services, Inc. or Executive Aircraft Services, Inc. client(s). Accordingly, you should rely on your own inspection of the aircraft. Any proposed transaction is subject to final execution of a contract acceptable in form and substance to Executive Aircraft Services, Inc., its client(s), and their counsel.





416-542-1059 Phone ◆ 416-564-1600 Cell ◆ 416-981-7674 Fax info@executive-aircraft.com





Specifications/Descriptions are provided as introductory information and do not constitute representations or warranties of Executive Aircraft Services, Inc. or Executive Aircraft Services, Inc. client(s). Accordingly, you should rely on your own inspection of the aircraft. Any proposed transaction is subject to final execution of a contract acceptable in form and substance to Executive Aircraft Services, Inc., its client(s), and their counsel.

> 416-542-1059 Phone ◆ 416-564-1600 Cell ◆ 416-981-7674 Fax info@executive-aircraft.com



6-542-1059 Phone 🎔 416-564-1600 Cell 🎔 416-981-7674 | info@executive-aircraft.com





Specifications/Descriptions are provided as introductory information and do not constitute representations or warranties of Executive Aircraft Services, Inc. or Executive Aircraft Services, Inc. client(s). Accordingly, you should rely on your own inspection of the aircraft. Any proposed transaction is subject to final execution of a contract acceptable in form and substance to Executive Aircraft Services, Inc., its client(s), and their counsel.

416-542-1059 Phone ◆ 416-564-1600 Cell ◆ 416-981-7674 Fax info@executive-aircraft.com





Specifications/Descriptions are provided as introductory information and do not constitute representations or warranties of Executive Aircraft Services, Inc. or Executive Aircraft Services, Inc. client(s). Accordingly, you should rely on your own inspection of the aircraft. Any proposed transaction is subject to final execution of a contract acceptable in form and substance to Executive Aircraft Services, Inc., its client(s), and their counsel.

> 416-542-1059 Phone ◆ 416-564-1600 Cell ◆ 416-981-7674 Fax info@executive-aircraft.com

